# DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt Kathleen Clarke **Executive Director** 

Lowell P. Braxton Division Director 801-538-7223 (TDD)

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax)

Partial: XXX Complete: \_\_Exploration: \_\_ Inspection Date & Time: 10/30/2001 / 2:00pm - 4:00pm Date of Last Inspection: 08/21/2001

Mine Name: Emery Deep Mine County	: Emery	Permit Numbe	r: <u>C/015/015</u>
Permittee and/or Operator's Name: Consolida	tion Coal Company		
Business Address: P.O. Box 566, Sesser, Illin	ois 62884		
Type of Mining Activity: Underground XXX	Surface P	Prep. Plant	Other
Company Official(s): Steve Behling			
State Official(s): Susan White	Federal Official(s)	: <u>None</u>	
Weather Conditions: Overcast and warm, few	rain drops		
Existing Acreage: Permitted 5180 Dist	irbed 247 Reg	graded	Seeded
Status: Active XXX			

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For <u>partial inspections</u> check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	<b>COMMENTS</b>	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	П		П	$\Box$
2.	SIGNS AND MARKERS	[X]	П	[X]	П
3.	TOPSOIL	[X]	$\Box$	[X]	$\Box$
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	$\Box$	[X]	Ц
	b. SEDIMENT PONDS AND IMPOUNDMENTS	Ш	Ц		Ц
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	Ц	[X]	
	d. WATER MONITORING	П		П	Щ
	e. EFFLUENT LIMITATIONS	Ц	П	Ξ	Ħ
5.	EXPLOSIVES	Ц	П	П	Ц
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	∐ -	Ц	Ц	Ħ
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS		Ц	Ц	H
8.	NONCOAL WASTE	П	П	$\Box$	Ц
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				F.3
	ENVIRONMENTAL ISSUES		П	Ц	Ц
	SLIDES AND OTHER DAMAGE		Ц	Ħ	П
	CONTEMPORANEOUS RECLAMATION	П	Ц	Ц	H
	BACKFILLING AND GRADING		Ц		
	REVEGETATION	П	Ц	Ļ	H
	SUBSIDENCE CONTROL		Ц		H
	CESSATION OF OPERATIONS	[X]	Ц	[X]	П
16.	ROADS:			<b>.</b>	r 1
	a. CONSTRUCTION/MAINTENANCE/SURFACING	П	Ц	Ц	
	b. DRAINAGE CONTROLS	Ц	Ц	Ц	
	OTHER TRANSPORTATION FACILITIES	Ц			
	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	П	[X]	Ц
	AVS CHECK (4 <sup>th</sup> Quarter- April, May, June)	Ц	Ц	Ц	П
	AIR QUALITY PERMIT	Ц			
21	RONDING & INSURANCE	ſΊ	1 1	1.1	1.1

#### INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/015/015

DATE OF INSPECTION: 10/30/2001

( COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE )

# 2. SIGNS AND MARKERS

The permit entry sign is located at the end of the public road and at entry into the disturbed area of the surface facilities.

# 3. TOPSOIL

The topsoil piles were untouched by the public road relocation. Topsoil piles had little vegetation.

#### 4A. HYDROLOGIC BALANCE: DIVERSIONS

A new culvert was installed during the upgrade of the haul road. This culvert should be shown on an asbuilt map.

#### 4C. OTHER SEDIMENT CONTROL MEASURES

All appropriate sediment controls were in place for the upgrading of the road.

# 15. CESSATION OF OPERATIONS

The Division has observed construction activities on the permit and disturbed area and will begin monthly inspections of the site. No official notice of resuming operations has been given to the Division by Consol.

#### 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

The county is upgrading the road to the mine. At the time of this inspection, road graders, compactors and gravel haul trucks were active on the permit area and disturbed area.

Inspector's Signature:

Susan M. White #35

Date: November 7, 2001

Note:

This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

White

cc:

James Fulton, OSM

Tim Kirschbaum, Consol, Illinois Steve Behling, Consol, Emery

Price Field office

O:\015015.EME\Compliance\2001\p\_1030.wpd